FMEA NO		SHUTTLE CCTV	UNIT <u>TVC/CLA</u> DNG NO. <u>2294819-506, 508/</u>	
		CAITICAL ITEMS LIST	2294821 <u>-563</u> SHEET <u>1</u> OF <u>8</u>	
CAUSE HODE AND	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANC		
iss of +28V Switched wer to the PTU.	Lass of PTH function.	DESIGN FEATURES		
Yorst Case: Loss of mission critical video.		The TVC/Lens Assembly is comprised of 16 electrical sears RCA Astro designed and fabricated using standard pronstruction. The remaining three assemblies, high verand stepper motors, are vandor supplied components whi purchased according to RCA Specification Control Drawing and reliability assurance. Specifications per establish the design, performance, test, qualification for a procured piece of equipment.	orinted-circuit board type of oltage power supply, oscillator, och have been specified and ongs (SCDs) prepared by engi- othe SCD are prepared to	
		Forts, materials, processes, and design guidelines for specified in accordance with RCA 2295503. This docume meats for selection and central of EEE parts. To the with availability, all parts have been selected from m JAN level, as a minimum. In addition to the everall a general purpose preferred parts has been defined by the ment Systems Division Standard Parts List. In the case microcircuits, devices are acreeded and tested to the procured under the designations of HI-REL/3WQ and SNC lastruments Corp, respectively. Parts not included in used in the design only after a nonstandard item appropared, submitted to Reliability Assurance Engineering the specific application(s) defined in the NSIAF by RA	ont defines the program require- maximum extent, and consistent dilitary specifications at the election criteria, a subset of is document and the ACA Severn- m of the CHOS and TTL family of MIL-STO-BBBC equivalent and S4LS from RCA-SSO and Texas the above documents have been val form (MSIAF) has been pre- dRAE) and approved for use to	
	·*•	Worst-Case Circuit Analyses have been performed and do designs to demonstrate that sufficient operating margi conditions. The analysis was worst case-in that the v parameters was set to limits that will drive the outpu	as exist for all eperating	
		A component application review and analysis was conduct stress on each piece part by the temperature extremes qualification testing does not exceed the stress derat 2295503.	dentified with soutropposts?	
<b>1</b>		In addition, an objective examination of the design was COR to verify that the TVC/Lens assembly met specifical ments.	s performed through a PDR and tion and contractual require-	
	1			
		•		

FHEA NO		SHUTTLE COTY CRITICAL ITEMS LIST	UNIT TYC/CLA DWG NO. 2294819-506, 508/ -2294821-503 SHEET 2 OF 8	
FAILURE HODE AMD FAILURE EFFECT		PATIONALE FOR ACCEPTANCE		
CAUSE ss of +28V Switched wer to the PTU.  Pawer On/Off Switching.	Loss of PTU Function.  Worst Case: Loss of mission critical video.	DESIGN FEATURES (Continued)  BARE BOARD DESIGN (A6)  The design of the associated A6 board is contructed freepoxy glass sheets (NEMA G-10) Grade FR-4), PER MIL-P-5 are made through printed traces which run from point to surfaces. Every trace terminates at an annular ring, the hale in which a component lead or terminal is locat a footing for the solder, ensuring good mechanical and its size and shape are governed by MIL-P-5560 as are t and routing. These requirements are raiterated specifits further assure compliance. Variations between the approduct (due to irregularities of the etching process) ing notes. This pravents making defective boards from house no lead or terminal, but serve only to electrical beard layers, contain stitch hars for mechanical support the thru holes are drilled from a drill tape thus eliminument error and allowing tight control over hole and an important reliability criterion. After drilling and et tim-lead plated per MIL-STD-1495. This provides for eather time and plated per MIL-STD-1495. This provides for eather time and house are assembly, even after periods of prolemon to provide stress relief and the bodies of I Special mounting and handling instructions are included after final assembly. The board is coated with wrether humidity and contamination.  BUARD REPLACEMENT  The Ab board is secured in the electronics assembly by copper card guides. Connections are made to the mother connectors. Disengagement during launch is prevented board's free edge.	point on the beard The annular ring surrounds ed. This ring provides electrical performance. race widths, spacing cally in drawing notes riwork master and the final are also controlled by draw- good artwork. Holes which Ty interconnect the different t and increased reliability.  mating the possibility of mular ring concentricity, an aching. All capper cladding is any and reliable soldering at anged storage.  maximum reliability.  of solder joints. All leads large components are staked. In each drawing required to which protects against  gold-plated beryllium r board with blind-mated	
	ı	1		

7 /دار د العجاز د المحجاد

MEA MO. 2.2.7		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT TVC/CLA DNG NO. 2294819-506.508/ 2294821-503 SHEET 3 OF 8
ATLURE HODE AND  CAUSE  s of +28V Switched ler to the PTU.  Power On/Off Switching.  FATLURE EFFECT OH END ITEM Loss of PTU function.  Worst Case: Loss of mission critical video.		QUALIFICATION TEST  For Qualification Test Flow, see Table 2 located at the front of this book.	
- }			

EA NO		CR1	SHUTTLE CCTV TICAL ITEMS LIST	UNIT
TLURE HODE AND	FAILURE EFFECT		RATIONALE FOR AC	CEPTANCE
of +28V Switched	Loss of PTU function.	ACCEPTANCE TEST	<del></del>	
r to the PTU.	Worst Case: Loss of mission critical	The CCTV systems, To pight be used in the	eir normal (astallation, to	_
Power On/Off Switching.	video.	• Vibration:	20-86Hz: 3 d8/0gt-ri 80-350 Hz: 0.04 6*/Hz 350-750 Hz: -3 d8/10 0c Test Duration: 1 Himute pe Test Level: 6.1 Grass	
		• Thermal Vacuum:	In a pressure of $1X10^{-5}$ Torfollows:	rr. the temperature shall be as
			125° F: Time to stablize of 125° F: Time to stablize of 125° F: Time to stablize of	equipment plus 1 heur
		The TVC/CLA may not	have been subjected to the	vacuum condition.
		for Acceptance Test	Flow, see Table 1 located	at the front of this book,
		OPERATIONAL TEST		
		health of all the c through the RCU, the decoder. The test ability to route vi	pumand related companents to rough the symp lines to the must also verify the capera	erational, a test must verify the row the PHS (A7A1) panel switch. Camera/PTU, to the Camera/PTU command 's ability to produce video, the YSU's ity to display video. A similar test ath.
		<u>Pre-Launch an</u>	Orbiter Test/In-Flight Tast	
		test as an 3. Send "Came 4. Select "Ex 5. Observe vi synchroniz is receivi synchroniz 6. Send Pan, via the m 7. Select do 8. Observe vi	IS panel, select a monitor a nurce, era Power On" command from Paternal Symc" on monitor, ideo displayed on monitor, and (i.e., stable raster) thing composite sync from the ted video.  Till, Focus, Zoom, DLN, AND emilor or direct observation emilink as destination and called routed to downlink.	Note that if video on wonitor is en this indicates that the camera RCU and that the camera is producing Gamma commands and visually (either o) verify operation.

THEA NO		SHUTTLE CCTV CRETICAL ITEMS LIST	ONG NO. 2294819-506, 508/ 2294821-503 SHEET 5 OF 8
FAILURE HODE AND CAUSE  SS OF +28V Switched wer to the PTU.  Power On/Off Switching.  FAILURE EFFECT ON END CTEM Loss of PTU Function.  Horst Case: Loss of mission critical vides.		RATIONALE FOR ACCEPTA	UKCE
		QA/INSPECTION  Procurement Control - The TVC/CLA EEE Parts and hard approved vendors and suppliers, which meet the requirement and Quality Plan Work Statement (WS-2593)? review all procurement documents to establish the ac (PAI 517).  Incoming Inspection and Storage - Incoming Quality received materials and parts. Results are recorded drawing and control numbers for future reference an are subjected to incoming acceptance tests as calle Inspection Test Jastructions. Incoming flight part accordance with RCA 1846684 - Preconditioning and A Electronic Parts, with the exception that DPA and P Hechanical items are inspected per PAI 316 - Incoming each accepted items are delivered to Haterial Contunder specified conditions until fabrication is required for Material Review Board (MRB) disposition.  Beard Assembly & Test - Prior to the start of TVC are verified to be correct by stock room personnel, form a kit. The items are verified again by the op checking against the as-built-parts-list (ABPI). Deared are designated for all printed circuit, wire wrap a harness connectors for soldering wiring, crioping, workmanship prior to coating of the compenent side harnesses.  IVC Boards  Specific TVC board assembly and test Instructions a applicable documents are called out in the Fabrication Formation of the compenent side harnesses.  IVC Boards  Specific TVC board assembly and test Instructions a applicable documents are called out in the Fabrication Formation of the compenent side harnesses.  IVC Boards  Specific TVC board assembly and test Instructions a applicable documents are called out in the Fabrication for soldering 2280749, Specific 2280878, Specification - Urathane coating 2280877, Specific 2280878, Specification - Workmanship 8030035, Specification - Workmanshi	dware items are procured from insments set forth in the CCTV 6). Resident OCAS personnel end for GSI on selected parts  inspections are made on all by lot and retained in file by d traceability. All EEE parts d for in PAI 315 - Incoming s are further processed in cceptance Requirements for INO testing is not performed. Inspection Instruction, and hased Parts Designated for Flight ralled Stores and retained uired. Non-conforming materials are (PAI-307, PAI IQC-531).  If CLA board assembly, all items as the items are accumulated to cerator who assembles the kit by CAS Handatory Inspection Points and welded wire boards, plus tolder splices and quality af boards and sleeving of  the provided in drawing notes, and clen Procedure and Record ude shuttle TVC assembly notes Standard - Bonding Valoro Iape ation - Bonding and Staking Specification - locking compound cification - Marking 2280876.

EA NO2.2.7		SHUTTLE CCTV CRITICAL ITEMS LIST	DHIT TVC/CLA  DWG NO. 2294819-506 508/ 2294821-503  SHEET 6 0F 8	
ILURE HODE AND	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE		
CAUSE  of +28V Switched  r to the PTU.  Power On/Off Switching.	AN END ITEM Loss of PTU Function.  Warst Case: Loss of mission critical video.	<u>IVC Assembly and Test</u> — An open box test is performed Acceptance Test per TP-AF-2294819, including vibration are specified and mitnessed, traceability numbers are are checked prior to use. RCA Quality and DCAS inspec completion of specified FPR operations in accordance we and PAI 217. OCAS personnel witness TVC button-up and <u>IVC/CtA Assembly and Test</u> — After a TVC and an CLA have they are mated and a final acceptance test is performed vibration and thermal vacuum anvironments. RCA and DC and review the acceptance test data/results. These performance after all repair, rework and retest.	per TP-I1-2294819, and an and thermal vacuum. Forques recorded and calibrated tools tions are performed at the ith PAI-204, PAI-205, PAI 206 critical torquing.  • has been tested individually, d per TP-AI-2294819, including AS personnel monitor these tests.	
		Preparation for Shipment — The TVC and CLA are separated fobrication and testing is complete. Each is packaged and 2280746, Process standard for Packaging and Handlidocumentation including assembly drawings, Parts List, gathered and held in a documentation folder assigned so this folder is retained for reference. An EIBP is preaccordance with the requirements of MS-2593176. RCA Q crating, packaging, packing, and marking, and review taccuracy.	according to CCTV Enter 2011 ng guidellnes. All related ABPL, Test Data, etc., is pecifically to each assembly. pared for each assembly in C and OCAS personnel witness	

	SHUTTLE CCTV CRITICAL IJEHS LIST	UNIT <u>IVC/CLA</u> DMG NO. <u>2294819-506</u> , 506/ <u>2294821-503</u> SHEET <u>7</u> OF <u>6</u>
FAELURE EFFECT ON END ITEM Loss of PTU function.  Vorst Case: Loss of mission critical videa.	FAILURE MISIORY  FOR - W274D - Log #0486 - TVC S/N 008-502  Description: Pre-Lawnch Test Failure Box Level Ambient Environment REF: VJCS-2-61-0097 unit returned from KSC. (+28V).  Cause: Incorrect wiring of shuttle craft hav RTN to J1-9.  Corrective Action: Wiring of shuttle harness	Power was applied to wrong pies.  These, put +28V to 31-10 and  I to be repaired by responsible  Towartive action taken on TVC
	tor - w6823 - Log #558 - TVC S/N 012-502 Y1771 - Log #568 - TVC S/N 009-502 Y1771 - Log #568 - TVC S/N 009-502 Y1771 - Log #568 - TVC S/N 002-502 Y1771 - Log #568 - TVC S/N 009-502 Y1770 - Log #567 - TVC S/N 014-502 Y1770 - Log #567 - TVC S/N 616-502 Y1770 - Log #568 - TVC S/N 617-582 Y1770 - Log #568 - TVC S/N 617-582 W1729 - Log #578 - TVC S/N 626-502	e replaced.
	Cause: Camera circuit breaker popped open our Cause: Camera low voltage supply has erratic temperature.  Corrective Action: All flight cameras were m and retest to ECH C-1881. \ ECM (C-1881) to the	syncronization mode at low eturned under CCA35 for rework to low voltage power supplies for group part no. has been
	Loss of PTU Function.  Vorst Case: Loss of mission critical	FAILURE EFFECT ON END ITEM.  Loss of PTU Function.  Worst Case: Loss of mission critical video.  FAILURE MESIDRY  FOR - W274D - Log #0486 - TVC S/N Q06-502  Description: Pra-Lawnch Test Failure Box Level Ambient Environment REF: VJCS-2-01-0097 unit returned from KSC. (+28V).  Cause: Incerrect wiring of shuttle craft have RTM to J1-9.  Corrective Action: Wiring of shuttle harnes: organization. Failure analysis performed and S/N 008. A6 hoard-failure analysis performed and schanged. Q1, Q3, Q12, CR3, CR6, and R51 were  TOR - W6823 - Log #558 - TVC S/N 012-502 Y1771 - Log #568 - TVC S/N 009-502 Y1771 - Log #568 - TVC S/N 009-502 Y1770 - Log #568 - TVC S/N 014-502 Y1770 - Log #568 - TVC S/N 014-502 Y1770 - Log #568 - TVC S/N 014-502 Y1770 - Log #568 - TVC S/N 017-582 W1729 - Log #578 - TVC S/N 017-582 W1729 - Log

HEA NO. 2.2.7  RITICALITY 2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT
AILURE NODE AND	FAILURE EFFECT	RATIONALE FOR ACCEPTANT	ie
CAUSE IS af +28V Switched Her to the PIU.  Power On/Off Switching.	Loss of PTU function.  Horst Case: Loss of mission critical video.	FAILURE HISTORY  TOR - W1760 - Log #0838 - TVC S/W 026-506  Description: Flight Failure, Spacecraft Level SIS-8  During the flight operations, one time when cre	
		Control of ALC and Gamma functions.  Problem resolved itself by recycling power.  Cause: After numerous operatoms, the reported set. After imitial turn on, commera would not elt was found that the output of USS Pin & CHD Fin a high state. This should normally have been but count 88 pulses, after initial power turn-of Suspect devices A2 - UZ6, U66, U67, and U68.	comdition was duplicated on test xcept ALC, and Gamma commands. .f. reset on A2 board was set n reset low by either "PGR" or
		Corrective Action: Removed and replaced the fe U26, U66, U67, and U68. Lab analysis did not i parts. Problem has not recurred after new part IDR - A3939 - Log #8954 - IVC S/N U31-506 Description: Flight Failure, Spacecraft Level STS-14 Problem report PV6-004037 No video output	USICSTED SOLA DRIBER MIKI LEBINAEN
		Cause: Defective Relay K-1 on the AG Board.  Corrective Action: Cause due to a foreign conductive particle temporarily lodged between relay leads and board P.C. traces. Relay K-1 sent to product assurance lab for analysis, report #A3909. Numerous discrepancies were found, none of which were critical.  IDR = B-3521 - Log #1165 - TVC S/N 038-508	
		<u>Bestription</u> : Acceptance Test failure dow Level Thermal Vac - Hot Envi Excessive supply current, lost all DLR/camera <u>Cause</u> : Shorted capacitor C14 on A6 board. <u>Corrective Action</u> : C14 removed and replaced w lab could not find a cause for shorted cap. ( Considered random failure.	ith new capacitor. Product assurar

FMEA NO		SHUTTLE CCTV CRITICAL ITEMS LEST	UNIT TVC/CLA DHG NO. 2294819-506. 508/ 2294821-503 SHEET 6 0F 8	
CRETICALITY 2/2				
FAILURE HODE AND	FATILURE EFFECT ON END ITEM	<u>RATIONALE FOR ACCEPTANCE</u>		
ass of +28V Switched	Loss of PTU function.	OPERATIONAL EFFECTS		
aver to the PTU.	<u>Worst Case</u> : Loss of mission critical	Possible loss of major mission objectives due to inabil desired fOV.	ity to position camera for	
<u>YC</u> <u>6</u> Pawer On/Off Switching.	videa.	CHEW ACTEON		
		If possible, continue mission using alternate visual co		
		CREW TRAINING		
	· [	Crew should be trained to use possible alternates to CCTV.		
		MISSION CONSTRAINT		
	. '	Where possible procedures should be designed so they c	an be accomplished without CCTV.	
			•	
	l			
·	1			
•				
	<u> </u>			
		•		
			·	
	Į.	1		
	1		·	
	Į.			
	i	<b>\</b>		
	•		-	

49200